


QuickControl

For use with infrared-enabled Ex-Or LightSpot HD sensors




Operating Instructions


General use





Start up



Battery Replacement



 The used battery must be disposed of in accordance with the applicable regulations.



Transmission Method: Infrared

Range: 15m approx

Battery: 3V DC CR2032 Lithium Button Cell

Expected Battery life: 3 years

Storage Temperature: -25oC to 70oC

Operating Temperature: 0oC to 40oC










IP Rating: 4X

Approval: CE

Dimensions: 100mm (h) x 50mm (w) x 7mm (d)

Weight: 45g approx

Functions

| | | |
|------------|---|--------------------|
| On/Off |  | Turn lights on/off |
| Brightness |  | Dim lighting |
| |  | Increase lighting |
| Scenes |  | Scene 1 |
| |  | Scene 2 |
| |  | Scene 3 |
| |  | Scene 4 |
| |  | Scene 5 |
| |  | Scene 6 |

Holster

Holster drill holes 45mm apart.
Countersunk screws No6 x 0.75" recommended (not supplied).

